

Figure 1




Figure 2




Figure 3






Figure 4



TOZOBO, TEEBIED



D9BEB351 DBOZO1







Figure 8














Figure 11a









| 389 | × | | | And the second s | | | | and | | | | | 350 | |
|--------|-------------------------|--|-------------------|--|-----------------|-------------------|---------------|---|---------------------|---------------------|------------------|------------------|-------------------|-------|
| 386 | | MOTO | Frequency | 58 | 51 | 26 | - | 10 | 8 | 9 | 2 | 5 | 2 | Close |
| 387388 | | list of the most likely causes for the specified SYMPTOM | Defect / | Defective Component | Test Error | Damaged | Broken Fiber | Pitted | Insufficient Solder | High Insertion loss | Excessive Solder | Proof Test Break | Wrong Component | |
| 38 | 🔑 Troubleshooting Guide | The following is a list of the m | Defect Category / | Component Defects | Testing Defects | Component Defects | Fiber Defects | Connector Defects | Solder Defects | Testing Defects | Solder Defects | Testing Defects | Component Defects | |

Figure 15